Crowcon Technical Note

Document Reference: **GEN066 – PC Communications Accessories for Portables**

Date: **14/11/2016**

Document applies to: **All Crowcon Portables**

This document provides an overview of the communications hardware accessories required to enable communication with a PC. For communications software requirements, please refer to GEN065.

	Crowcon Clip
Accessories Required	CC-IR-LINK

	Gas Pro, **T4**
Accessories Required	Either of these: CH0103, USB communications lead (not powered) CH0104, USB dual communication and power lead (charges from USB port)

Copyright© 2015 Crowcon Detection Instruments Ltd.
All rights reserved. Company registered no. 978878

Crowcon Technical Note

	Gasman
Accessories Required	C01940, Single way charger/interface 12Vdc input C03580, Multi-region power supply E07532, PC lead (9 way D, female to female) C02097, USB to RS232 adaptor (if connecting to USB port)
Accessories also available as a kit	**C011305**, Charger interface kit (includes all of the above)

Crowcon Detection Instruments Ltd
172 Brook Drive, Milton Park, Abingdon, Oxfordshire, OX14 4SD, UK
Email: customersupport@crowcon.com Web: www.crowcon.com

Copyright© 2015 Crowcon Detection Instruments Ltd.
All rights reserved. Company registered no. 978878

Crowcon Technical Note

	Tetra 3
Accessories Required	C011019, Single way charger/interface 12Vdc input C03580, Multi-region power supply E07532, PC lead (9 way D, female to female) C02097, USB to RS232 adaptor (if connecting to USB port)
Accessories also available as a kit	**C011306**, Charger interface kit (includes all of the above)

Crowcon Detection Instruments Ltd
172 Brook Drive, Milton Park, Abingdon, Oxfordshire, OX14 4SD, UK
Email: customersupport@crowcon.com Web: www.crowcon.com

Copyright© 2015 Crowcon Detection Instruments Ltd.
All rights reserved. Company registered no. 978878

<table>
<tr><td></td><td> Triple Plus +</td></tr>
<tr><td>Accessories Required</td><td>Charger Interface for the appropriate region:
<table><tr><td>C01439</td><td>Charger/Interface II for Australia only</td></tr><tr><td>C01438</td><td>Charger/Interface II for Europe only</td></tr><tr><td>C01626</td><td>Charger/Interface II for South Africa only</td></tr><tr><td>C01436</td><td>Charger/Interface II for UK only</td></tr><tr><td>C01437</td><td>Charger/Interface II for USA only</td></tr><tr><td>C01440</td><td>Charger/Interface II international without plug</td></tr></table>
C01327, Computer lead assembly 9 way to 9 way
C02097, USB to RS232 adaptor (if connecting to USB port)

 </td></tr>
</table>

Crowcon Detection Instruments Ltd
172 Brook Drive, Milton Park, Abingdon, Oxfordshire, OX14 4SD, UK
Email: customersupport@crowcon.com Web: www.crowcon.com

Copyright© 2015 Crowcon Detection Instruments Ltd.
All rights reserved. Company registered no. 978878

Crowcon Technical Note

	Detective +
Accessories Required	E07394, Computer lead assembly C02097, USB to RS232 adaptor (if connecting to USB port)

	Tetra
Accessories Required	E07985, IR adaptor for PC (plugs into RS232 port) C02097, USB to RS232 adaptor (if connecting to USB port)

For further information please contact us at customersupport@crowcon.com +44 (0)1235 557711

Copyright© 2015 Crowcon Detection Instruments Ltd.
All rights reserved. Company registered no. 978878