


Universal Centre Finder with Indicator.

Features

- For finding the centre of a bore or to measure the concentricity of a work piece
- Indicator always faces the operator, regardless of turning spindle
- With double indicator for maximum resolution
- For vertical or horizontal use
- Includes six different touch points for internal and external measurements



Specification

Code No	Range - Internal (mm)	Range - External (mm)	Concentricity (mm)	Accuracy (mm)	Indicator Range (mm)
MW612-01	3.5-300	0-300	0.005	0.01	0-3