







# Comfortable testing of screw tops, e.g. bottles, jars

#### **Features**

- II Optimised for torque testing of bottles, jars and other packaging with screw tops, e.g. in the food industry and pharmaceutical industry, as well as in the manufacturing of cosmetics such as, for example, lipsticks, etc.
- 2 Quick pin system: The four bottle mounts (holders) are pushed in, instead of being screwed in, to save time. This allows you to reconfigure quickly for other bottle sizes
- · Metal housing for continuous use in tough environmental conditions
- 3 Capacity display: A bar lights up to show how much of the measuring range is still available.
- 3 LCD graphics display with backlight
- · Rubber feet with anti-slip feature

- Scope of delivery: four bottle mounts with rubber coat, sturdy carrying case
- Internal data memory saves up to 500 measurements. The memory contents can be transferred to the PC using optional software
- 4 USB and RS-232 data interfaces included
- Peak hold function to capture the peak value or Track function for continuous display of measurement
- · Can be used in both directions of rotation
- · Measuring with tolerance range (limit-setting function): Upper and lower limiting can be programmed individually. The process is supported by an audible and visual signal
- AUTO-OFF function

#### **Technical data**

- · Selectable units: Nm, lbf-in, kgf-cm, kgf-m, ft-lbf
- Precision: ± 0,5 % of [Max]
- · Measuring frequency: 1000 Hz
- Usable measuring range: 5-100 % of [Max]
- Overload protection: 150 % of [Max]
- Rechargeable battery pack integrated, standard, operating time up to 18 h without backlight, charging time approx. 14 h
- Overall dimensions W×D×H 250×160×100 mm
- Net weight approx. 3 kg

### **Accessories**

- Plug-In for data transfer of measuring data from the measuring instrument and transfer to a PC, e.g. in Microsoft Excel®, SAUTER AFI-1.0
- Force-time data transfer software for graphical representation on the PC and data transfer to Microsoft Excel®, SAUTER AFH FAST
- · RS-232/PC connection cable SAUTER FL-A04
- USB/PC connection cable SAUTER FI-A01

S	TA	۱N	ID	Α	R	
	_		_	_	_	

























Model Measuring range Readout Option Diameter Factory calibration certificate test object [Max] [d] **SAUTER** KERN NmNmmm DA 1-4 0,0002 10-165 961-120 DA 5-3 5 0,001 10-165 961-120 DA 10-3 10 0,002 10-165 961-120

# **SAUTER Pictograms:**





#### Adjusting program (CAL):

For quick setting of the balance's accuracy. External adjusting weight required.



# Control outputs

#### (optocoupler, digital I/O):

to connect relays, signal lamps, valves, etc.



#### Rechargeable battery pack:

rechargeable set.



PEAK

#### Calibration block:

Peak hold function:

measuring process.

standard for adjusting or correcting the measuring device.



#### Analogue interface:

to connect a suitable peripheral device for analogue processing of the measurements.



#### Mains adapter:

230V/50Hz in standard version for EU. On request GB, AUS or USA version available.



#### Statistics:

using the saved values, the device calculates statistical data, such as average value, standard deviation etc.



## Power supply:

Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.



### Motorised drive:

The mechanical movement is carried out by a electric motor.



SCAN

# Scan mode:

Push and Pull:

continuous capture and display of measurements.

capturing a peak value within a



PRINT

# PC Software:

Printer:

to transfer the measurements from the device to a PC.

a printer can be connected to the

device to print out the measurements.



Motorised drive: The mechanical movement is carried out

by a synchronous motor (stepper).

DAkkS calibration possible:

is shown in days in the pictogram.



#### Length measurement:

and compression forces.

captures the geometric dimensions of a test object or the movement during a test process.

the measuring device can capture tension



### GLP/ISO record keeping:

of measurements with date, time and serial number. Only with SAUTER printers.



#### Fast-Move:

the total length of travel can be covered by a single lever movement.



MEMORY

#### Focus function:

Internal memory:

to save measurements

in the device memory.

increases the measuring accuracy of a device within a defined measuring range.



#### Measuring units:

Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.



# Measuring with tolerance range

(limit-setting function): Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model





DAkkS

+3 DAYS

#### Factory calibration:

The time required for factory calibration is specified in the pictogram.

The time required for DAkkS calibration



#### Data interface RS-232:

bidirectional, for connection of printer and PC.



Resets the display to "0".



### Package shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



# Pallet shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



#### Data interface USB:

To connect the balance to a printer, PC or other peripheral devices.



## Data interface Infrared:

To transfer data from the balance to a printer, PC or other peripheral devices.



# **Battery operation:**

Ready for battery operation. The battery type is specified for each device.

